

SUMMER STEM CAMP: MACHINE TOOLS IN ENGINEERING

GENERAL SAFETY INFORMATION

1. No Horseplay
2. Always listen to your instructors
3. If you're unsure of something...Ask Questions!!
4. Never leave a running machine unattended
5. Always be aware of rotating equipment
6. Never stop a spindle with a bare hand
7. Be careful when handling metal chips. They can be extremely sharp. Pulling on a long string can result in a cut.
8. Be respectful of your fellow students.
9. Never put a rag near a rotating spindle
10. Always be aware of your surroundings

11. HAVE FUN!!!

You're required to...it's in the rules!

SPONSORS



Haas Automation Inc.



The Convenience Stores For Metal®

PURDUE
UNIVERSITY

FORT WAYNE

REQUIRED CLOTHING

Closed toe shoes
Short sleeve shirt

You will be working with oil's, layout dye, and machinery. Make sure you are wearing clothes that can get dirty.

REQUIRED SAFETY GEAR

Safety Glasses



DON'TS

No Dangling Jewelry (dangling earrings, necklaces, bracelets)

No Rings

Long hair must be pulled back and tied up so it doesn't dangle at all.